

Nov 2014

The P4015 Fuser Drive Asm (RC2-2432)



Customers have been asking about installing the HP P4014/4015/4515 series fuser drive assembly in the HP M600 series printers. We have been told that after doing web searches and checking on various web sites, they have found the drives are interchangeable. Unfortunately that is not the case.

The gears on both the fuser and fuser drive are different. On the HP P4014/4015/4515 series printers the gears are spur gears or straight cut style gears. On the M600 series printers the gears are helical gears or angle cut style gears. Installing the incorrect drive in a printer will result in the fuser gear getting damaged and replacing the fuser becoming necessary.

As of right now HP doesn't offer a fuser drive for the M600 series printer. However the RC2-2432 will work in the M4555 printer.

The RC2-2432 fuser drive assembly will work in the following printers:

- P4014
- P4015
- P4515
- M4555



p4015



m600 series

Parts on Demand Limited.

14A Clemway Place
Henderson, Waitakere 0610
PO Box 104229, Lincoln North 0654
AUCKLAND, NEW ZEALAND

Phone: 64 9 8366602
Fax: 64 9 8366604
Free Phone: 0800 225505
Email: support@partsondemand.co.nz